566 and 568 **Multipurpose Thermometers**



Fluke 568



The Fluke 566 and included accessories



The Fluke 568 and included accessories

Included accessories

FlukeView® Forms software (568 only), USB cable (568 only), K-type thermocouple bead probe, 2 AA batteries, hard carrying case, quick start guide, and users manual.

Ordering information

Fluke 566	Infrared thermometer
Fluke 568	Infrared thermometer

The two-in-one infrared and contact thermometer with an innovative graphical display

With a straight-forward, menu-driven user interface and graphical display, the Fluke 566 and 568 multipurpose thermometers make even complex temperature measurements easy. Quickly navigate and adjust emissivity, start data logging, or turn on and off alarms, with just a few pushes of a button. For added convenience, both rugged handheld thermometers combine contact and non-contact temperature measurement capability, providing a total temperature measurement solution for any service and maintenance program.

· Easily access advanced features with the soft-key buttons and graphical display

- Measure smaller targets from farther away using the IR thermometer
- Adjustable emissivity and built-in table of common materials for higher IR accuracy
- Quickly identify problems with the MIN, MAX, AVG, and DIF functions
- 2-color flashing alarm alerts you visually when measurements exceed limits
- · Includes Type K thermocouple bead probe · Compatible with all standard mini-
- connector K-type thermocouples Data logging with a date/time stamp
- Soft rubber boot for increased ruggedness
- User interface available in 6 languages



Choose your language

 Enter Back Select the measurement surface

Default Ox Aluminum

Ox Brass

Ox Copper

£=0.50 (IIII



See complete measurement details in seconds

Product specifications

(Check the Fluke web for detailed specifications)

	566	568	
Infrared temperature range	-40 °C to 650 °C	-40 °C to 800 °C	
Infrared accuracy	< 0 °C : ± (1.0 ° > 0 °C : ± 1 % or ± 1	< 0 °C : ± (1.0 °C + 0.1°/1 °C); > 0 °C : ± 1 % or ± 1.0 °C, whichever is greater	
Display resolution	0.1 °C		
Infrared spectral response	8 μm to	8 µm to 14 µm	
Infrared response time	< 500	< 500 msec	
Input temperature range	-270 °C to	-270 °C to 1372 °C	
Input accuracy		-270 °C to -40 °C: ± (1 °C + 0.2 °/1 °C) -40 °C to 1372 °C: ± 1 % or 1 °C, whichever is greater	
D:S (Distance to measurement spot size)	30:1	50:1	
Laser sighting	Single-point laser < 1 mw output Class 2 (II) operation, 630 nm to 670 nm		
Minimum spot size	19 mm		
Emissivity adjustment	By built-in table of common materials or digitally adjustable from 0.10 to 1.00 by 0.01		
Data logging with Date/Time stamp	20 points	99 points	
PC interface and cable	None	USB 2.0 with FlukeView [®] Forms software	
Hi/Low alarms	Audible and two-color visual		
Min/Max/Avg/Dif	Ye	Yes	
Display	Dot matrix 98 x 96 pi	Dot matrix 98 x 96 pixels with function menus	
Backlight	Two levels, normal ar	Two levels, normal and extra bright for darker environments	
Trigger Lock	Ye	Yes	
Switchable between Celsius and Fahrenheit	Yes		

Power: 2 AA/LR6 Batteries (566); 2 AA/LR6 Batteries and USB for use with a PC (568) Battery life: Used continuously; laser and backlight on: 12 hours; laser and backlight off: 100 hours

Weight: 0.965 kg (566); 1.026 kg (568) Size (HxLxW): 25.4 cm x 19.1 cm x 6.9 cm Operating temperature: 0 °C to 50 °C Storage temperature: -20 °C to 60 °C Two years warranty



